

BEFORE THE ARIZONA CORPORATION COL RECEIVED

COMMISSIONERS

1

2

8

9

10

11

12

13

14

15

16

MIKE GLEASON, Chairman 3 WILLIAM A. MUNDELL 4

JEFF HATCH-MILLER KRISTIN K. MAYES

GARY PIERCE 5

→ 2007 NOV 20 P 2: 21

AZ CORP COMMISSION DOCKET CONTROL

IN THE MATTER OF THE APPLICATION OF CORDES LAKES WATER COMPANY FOR APPROVAL OF A WATER COMPANY RATE REVIEW STATEMENT OF RATE BASE

DOCKET NO. W-02060A-07-0256

STAFF'S LATE-FILED EXHIBIT

The Arizona Corporation Commission Utilities Division ("Staff"), files this updated compliance status report from the Arizona Department of Environmental Quality, dated November 19, 2007.

RESPECTFULLY submitted this 20th day of November, 2007.

Attorney, Legal Division 1200 West Washington Street Phoenix, Arizona 85007 Telephone: (602) 542-3402

17

18

19

of the foregoing were filed this 20 20th day of November, 2007 with:

21

Docket Control

Arizona Corporation Commission 22 1200 West Washington Street

Original and thirteen (13) copies

Phoenix, Arizona 85007 23

Copy of the foregoing mailed this 24 20th day of November, 2007 to:

25

28

Lee E. Esch. Esa.

Jennings Strouss & Salmon, PLC 26 201 E. Washington Street, 11th Floor

27 Phoenix, Arizona 85004

Arizona Corporation Commission DOCKETED

NOV 20 2007

DOCKETED BY

Mr. Neil Folkman Authorized Representative Cordes Lakes Water Company 2501 East Palo Verde Phoenix, Arizona 85016

30E

Arizona Department of Environmental Quality

Drinking Water Monitoring and Protection Unit 1110 W. Washington Street, 5415B-1 Phoenix, AZ 85007

Drinking Water Compliance Status Report

Public Water System Name:	Cordes Lakes Water Co.		
Public Water System ID #:	13-023		
Public Water System Type:	[X] Community [] Nor	n-transient Non-community	[] Transient Non-community
Overall Compliance Status:	[X] No Major Deficiencies [] Major Deficiencies		s
Monitoring and Reporting Status: Comments:	[X] No Major Deficiencie	es [] Major Deficiencie	s
The system has five treatment plants an products rule (DBP), but had not provide monitoring for this system was completed federal standards. As such, all historic system will need to take five samples be rule.	ed any analyses for 2005 d in October 2007, and al DBP monitoring violation	i and 2006. At the request of I DBP-related analytical resul is have been returned to cor	f the Department, annual DBF its for the testing met state and appliance as of 11/19/07. The
Operation and Maintenance Status: Comments: None	[X] No Major Deficiencie	es [] Major Deficiencies	s
Major unresolved/ongoing operation and [] unable to maintain 20 [] cross connection/back [] treatment deficiencies [] certified operator	osi kflow problems [] surfac	es: [] inadequate storage ce water treatment rule eval of construction [] other	
Date of last inspection / sanitary survey:	9-16-04		
Administrative Orders: Is an ADEQ administrative order in effect Comments: None	t? [] Yes	[X] No	
System information:			
Number of Entry Points to the Distributio	n System <u>5</u>	Number of Sources 4	
Population Served 3050 Service	Connections 1333	Initial Monitoring Year 1995	5
			17

Evaluation completed by: <u>Donna Calderon, Manager, Drinking Water Monitoring and Protection Unit</u>
Phone: <u>602-771-4641</u> Date: <u>November 19, 2007</u>

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.